

## CTS Home Watch 4401 South Summerview Circle Bountiful, UT 84010

## Services by: Tomas Ratto

Services provided on visit:	Outcome	Notes	Recommendation
		1) Door leading from kitchen to garage was	
		locked. Last week this door was previously left	
		unlocked. We are not sure if you prefer that	
		Door to be locked or unlocked. At this point We	
		left it locked. Please let us know if you want it	
		left unlocked.	
		2) Window closest to fireplace in basement was unlocked. The window was closed but was left	
Doors and windows locked		unlocked. Window has now been locked.	
Forced entry Review		unlocked. Willdow has now been locked.	
Snow & Lawn Care Survey			
Food Disposal System Run			
		It was advised to us that the heat would be left	
		at 62 degrees. However the main floor is set at	
		62 but the basement is currently set at 60. Is	
Air Conditioner and Heating Set		this the desired temperature?	
			Suggestion to move
			forward with
			replacement. We
Water Heater		Water Heater is dripping.	can set install date upon your approval
Smoke detector Sound Check		water rieater is uripping.	apon your approvar
Visual Ceiling Water Leak			
Refrigerator Check			
Bedroom Inspection			
Bathroom Inspection			
Sink & Toilet Flush			
Electrical Service Panel Check			
Room lighting/timers Set		Light inside the garage was left on. Now it's off.	
General Home Cleanliness check			
Tub/Shower Check			
Visually Inspection for			
pests/insects/rodents			
Flyers/Newspaper Removal			
Home securely locked upon			
completion of inspection			
Pictures of issues sent to Owner		Water Heater photos attached in email	

## **General Comments:**